

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Jim Smith Environmental Scientist III				
Company	Dennis Oakley Environmental Engineer				

Inspection Report

Permit Number:	C0150017		
Inspection Type:	COMPLETE		
Inspection Date:	Friday, June 25, 2004		
Start Date/Time:	6/25/2004 8:30:00 AM		
End Date/Time:	6/25/2004 12:39:00 PM		
Last Inspection:	Tuesday, May 25, 2004		

Inspector: Jim Smith, Environmental Scientist III Weather: Cloudy, thundershowers nearby but no rain.

InspectionID Report Number: 313

Accepted by: dhaddock

6/30/2004

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages		Mineral Ownership	Types of Operations		
154.86	Total Permitted	✓ Federal	✓ Underground		
23.88	Total Disturbed	✓ State	Surface		
	Phase I	☐ County	Loadout		
	Phase II	✓ Fee	Processing		
	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature

Jim Smith, Environmental Scientist III

Inspector ID Number: 43

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Monday, June 28, 2004

Date

Permit Number: C0150017 Inspection Type: COMPLETE

Inspection Date: Friday, June 25, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark			
2.	Signs and Markers	✓		✓	
3.	Topsoil	V			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		~	
4.c	Hydrologic Balance: Other Sediment Control Measures	V			
4.d	Hydrologic Balance: Water Monitoring	V			
4.e	Hydrologic Balance: Effluent Limitations	V			
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	✓			
13.	Revegetation	V		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.a	Roads: Construction, Maintenance, Surfacing	✓		V	
16.Ł	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		V		
19.	AVS Check	✓			
20.	Air Quality Permit		V		
21.	Bonding and Insurance	V			
22.	Other		V		

Permit Number: C0150017 Inspection Type: COMPLETE

Inspection Date: Friday, June 25, 2004

Page 3 of 3

2. Signs and Markers

A paper sign in plastic lamination has been placed over the metal sign at the entry to the sedimentation pond road. Bullet holes have made the metal sign unreadable.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

There has been no discharge during the second quarter. The pond is dry, but Dennis says the sediment is still soft under the crust. Sediment will be removed this month to bring storage capacity back to within design limits.

13. Revegetation

Revegetation is progressing, better in some areas than in others. The bathhouse slope looks barren from the cattle trail, but on closer examination, shadscale and grasses are growing in the pocks. Some cheat grass and a lot of halogeton in places, especially along the cattle trail.

16.a Roads: Construction, Maintenance, Surfacing

The road to the sedimentation pond is the only road remaining. It receives minimal traffic and minimal maintenance.